



2025-12-17 11:55:53
40.1101189, -85.6561348
[View Image](#)



2025-12-17 11:55:59
40.1101189, -85.6561348
[View Image](#)



2025-12-17 11:56:04
40.1101189, -85.6561348
[View Image](#)



2025-12-17 11:56:10
40.1101189, -85.6561348
[View Image](#)

Hallway/Stairs

Detail	Condition	Actions	Comment
Closet/Cabinet	✓ S	None	
Flooring/Baseboard	✓ S	None	
Light Fixture	✓ S	None	
Other	✓ S	None	
Railing/Banister	✓ S	None	
Smoke/CO Detector	✓ S	None	
Switch/Outlet	✓ S	None	