



2025-12-17 11:58:16
 40.1098151, -85.6564703
[View Image](#)



2025-12-17 11:58:21
 40.1098151, -85.6564703
[View Image](#)

Bedroom 2: 2nd bedroom on left

Detail	Condition	Actions	Comment
Closet/Door/Track/Shelving	✓ S	None	
Door/Knob/Lock	✓ S	None	
Flooring/Baseboard	✓ S	None	
Light Fixture/Fan	✓ S	None	
Other	✓ S	None	
Switch/Outlet	✓ S	None	
Wall/Ceiling	✓ S	None	
Window Covering	✓ S	None	
Window/Lock/Screen	✓ S	None	
Smoke Detector	✓ S	None	