



2025-12-17 12:00:10  
 40.1101267, -85.656137  
[View Image](#)



2025-12-17 12:00:13  
 40.1101267, -85.656137  
[View Image](#)



2025-12-17 12:00:15  
 40.1101267, -85.656137  
[View Image](#)

## Bathroom 2: Near garage

| Detail                   | Condition | Actions | Comment |
|--------------------------|-----------|---------|---------|
| Cabinet/Counter/Shelving | ✓ S       | None    |         |
| Door/Knob/Lock           | ✓ S       | None    |         |
| Exhaust Fan              | ✓ S       | None    |         |
| Flooring/Baseboard       | ✓ S       | None    |         |
| Light Fixture            | ✓ S       | None    |         |
| Medicine Cabinet/Mirror  | ✓ S       | None    |         |
| Other                    | ✓ S       | None    |         |