



2025-11-25 08:15:18  
40.110116, -85.6560896  
[View Image](#)



2025-12-17 11:54:55  
40.1101189, -85.6561348  
[View Image](#)



2025-12-17 11:54:57  
40.1101189, -85.6561348  
[View Image](#)



2025-12-17 11:55:05  
40.1101189, -85.6561348  
[View Image](#)

## Other Room: Back foyer connecting garage and dining room

| Detail             | Condition | Actions | Comment |
|--------------------|-----------|---------|---------|
| Door/Knob/Lock     | ✓ S       | None    |         |
| Flooring/Baseboard | ✓ S       | None    |         |
| Light Fixture/Fan  | ✓ S       | None    |         |
| Other              | ✓ S       | None    |         |
| Switch/Outlet      | ✓ S       | None    |         |
| Wall/Ceiling       | ✓ S       | None    |         |
| Window Covering    | ✓ S       | None    |         |