



2025-11-25 08:34:01
40.1100167, -85.6560882
[View Image](#)



2025-12-17 12:09:42
40.1096594, -85.6567583
[View Image](#)



2025-12-17 12:10:04
40.1096594, -85.6567583
[View Image](#)

Living Room

Detail	Condition	Actions	Comment
Door/Knob/Lock	✓ S	None	
Fireplace Equipment	✓ S	None	
Flooring/Baseboard	✓ S	None	
Light Fixture/Fan	✓ S	None	
Other	✓ S	None	
Switch/Outlet	✓ S	None	
Wall/Ceiling	✓ S	None	