


Dining Room

Detail	Condition	Actions	Comment
Flooring/Baseboard	✓ S	None	
Light Fixture/Fan	✓ S	None	
Other	✓ S	None	
Smoke/CO Detector	✓ S	None	
Switch/Outlet	✓ S	None	
Wall/Ceiling	✓ S	None	
Window Covering	✓ S	None	
Window/Lock/Screen	✓ S	None	



2025-11-25 08:09:50
40.1101217, -85.6560535
[View Video](#)



2025-11-25 08:09:54
40.1101217, -85.6560535
[View Image](#)